




PART NUMBER 70258

DIN RAIL SINGLE PHASE 110-240 VAC SOFT START

RECOMMENDED FOR:

PBA 30
PBA 50
PBA 60
PBA 120
PBW 150
PBW 300
PBW 450



Note:

The device may not be necessary on smaller generators if slo-blo line fuses are sized significantly above the running current. The soft start is necessary for fuses sized close to the running current. Because of the wide variety of fuse types it is not feasible to offer a more specific recommendation.